

# マスキング手順を考えよう

1.



0V

5V

20V

① 低電圧 → 高電圧

② 高電圧 → 低電圧

2.




0V

5V

90V

3.



0V

10V

15V

35V

45V